



More information on the website
radwag.com/en/info,w1,PES

PUE H315 Indicator



Functions



Plus/Minus Control



Percent Weighing



Totalizing



Parts counting



Internal battery



Peak hold



Newton unit
measurement



GLP Procedures



Animal weighing



ALIBI Memory

Datasheet

Metrological parameters	
Maximum quantity of verification units	6000 e
OIML Class	III
Maximum quantity of divisions from converter	838 860 ×10
Maximum increase of signal	39 mV
Minimum volatge per verification unit	0,4 µV
Maximum voltage per verification unit	3,25 µV
Minimum load cell impedance	50 Ω

Metrological parameters	
Maximum load cell impedance	1200 Ω
Load cell excitation voltage	5V DC
Connection of load cells	4 or 6 wires + shield
Physical parameters	
Display	LCD (backlit)
Device dimensions	208×145×80 mm
Packaging dimensions	300×250×130 mm
Net weight	1,9 kg
Gross weight	2,7 kg
Protection class	IP 66 / IP 67 / IP 69
Number of buttons	5
Multiple range	1 or 2 ranges
Additional LCD display	WD-4/1 (option)
Communication interface	
USB Interface	1
RS232 Interface	1
Optional interfaces	RS232 or RS485 or 4IN/4OUT or Ethernet or analog output 4-20 mA
Electrical parameters	
Power supply	100 – 240 V AC 50 / 60 Hz and battery *
Operation time on batteries	max 7h
Environmental conditions	
Operating temperature	-10 ÷ +40 °C
Storage temperature	-10 ÷ +50 °C
Relative humidity	10% ÷ 80% RH no condensation
Construction	
Keypad	microswitch
Housing	stainless steel



Compatible with

Waterproof stainless steel platforms
Mild steel powder coated weighing platforms
Receipt Printer
RS 232 cables (scale - EPSON printer)
Mild steel powder coated weighing platforms
Stands, wall mounting kits and mounting brackets
RS 232 cables (scale - Ethernet)

RS 232, RS 485 cables
USB adapter
USB cable (scale - printer)
RS 232 – USB Converter
Displays
RS 232 – RS 485 Converter

Software

RAD-KEY
LabVIEW Driver

RW Tool
R Panel

Device dimensions

